



ASPECT
Satin

COVERAGE
500 ml = ± 6 sq.m per coat

DRYING TIME
BETWEEN COATS
12 H

COMPLETE DRYING
TIME
24 H

ΑΠΕΥΘΕΙΑΣ ΕΦΑΡΜΟΓΗ
ΣΤΗΝ ΕΠΙΦΑΝΕΙΑ
DIRECT ON SUPPORT



Size: 500 ml

This paint is designed for the renovation of any **electrical convectors and radiators made of metal, aluminium, iron cast...**

EASY, FAST and EFFICIENT !

- 2 in 1 NO UNDERCOAT
- PERFECT TENSE.
- Does not flake - the paint film is highly durable to temperature variations
- Resistant to stains and impacts.
- Washable.
- Water-based paint.

COLOURCHART





Renovation RADIATORS

FOR A SUCCESSFUL PROJECT

This paint is designed for electrical convectors, radiators and central heating plumbing.

Surface PREPARATION is ESSENTIAL. See step 1 below.

Optimum product performance and adhesion is achieved after 20 days from application. Treat the surface gently, avoiding direct impact, abrasion, staining or cleaning, for the first 20 days after application.

> STEP 1 - PREPARATION

- **On ALUMINIUM, METAL, IRON CAST:**

Degrease with acetone and allow to dry.

- **On ALUMINIUM, METAL, IRON CAST** already painted with an old paint (solvent based) or on small PLASTIC surfaces :

Wash, rinse thoroughly with water, allow to dry then lightly sand (240 grit) and remove dust..

WASHING the surface with a soda-based (alkaline) cleaner is essential..

Greasy or plastic-coated surfaces can affect the adhesion of the paint..

> STEP 2 - APPLICATION

TOOLS : Paint mixer or wide stick • Paint roller & brush (for angles, corners, joints & finishes)

Before applying, stir the paint with a mixer or wide stick, working around the bottom of the tin to mix it well.

This is a ready-to-use product, do not dilute.

1. Start by painting the angles, corners and joints of the surface with a brush.
2. Distribute the paint evenly on a roller and apply the paint with vertical strokes. Follow with successive horizontal strokes, perpendicular to those just applied.
3. Finish with further vertical strokes for perfect results.

To achieve the best results in terms of performance and resistance, two coats of paint are essential. Touch dry: 2 hours - Recoat: 12 hours - Fully dry: 24 hours. For bright colors, dark or porous surfaces, it may be necessary to apply an additional coat.

Interior use only • Before applying the paint, cover any areas of the surface or surroundings that are not being painted • Work on small surfaces (0.5-1m²) • Do not exceed the recommended coverage rate • Do not apply the product either too thickly or too thinly • Apply the paint between 12 and 25 °C and avoid draughts • Do not stop applying the product in the center of a surface • Do not start reapplying the product while it's still drying • Remove as much paint as possible from brushes and rollers before washing. Clean your tools with water • To clean painted surfaces, use a gentle detergent. Do not use abrasive sponges.